
Construction Updates




December 2022



Activity	A 1
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%




Activity	A2
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%




Expected possession – 31/12/2023

Activity	A3
RCC	100%
Blockwork	95%
External Plaster	0%
Wall Conduit	100%
External Plumbing	0%
Conceal Plumbing	100%
Fabrication	80%
Water Proofing	83%
Gypsum	90%
Flooring	22%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	0%



Expected possession – 31/12/2023


Activity	A 4
RCC	100%
Blockwork	95%
External Plaster	0%
Wall Conduit	100%
External Plumbing	0%
Conceal Plumbing	100%
Fabrication	90%
Water Proofing	83%
Gypsum	90%
Flooring	27%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	0%



Activity	A5
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	95%
Door	100%
Wire & Switch work	90%
Internal Paint	70%
External Paint	70%
Snag	55%
Lift	100%



Activity	A 6
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	90%
Door	100%
Wire & Switch work	80%
Internal Paint	65%
External Paint	70%
Snag	53%
Lift	100%



Activity	A 7
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	95%
Door	100%
Wire & Switch work	95%
Internal Paint	53%
External Paint	75%
Snag	53%
Lift	100%




Activity	A8
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	95%
Door	100%
Wire & Switch work	95%
Internal Paint	60%
External Paint	70%
Snag	55%
Lift	100%



Activity	A9
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	86%
Internal Paint	70%
External Paint	70%
Snag	55%
Lift	100%



Activity	A10
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	97%
Wire & Switch work	90%
Internal Paint	67%
External Paint	70%
Snag	73%
Lift	100%



Activity	B1
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%



Activity	B2
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%



Activity	В3
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%



Activity	B4
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%




Activity	B5
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	90%
Gypsum	95%
Flooring	100%
Window	55%
Door	80%
Wire & Switch work	40%
Internal Paint	0%
External Paint	80%
Snag	40%
Lift	25%



Activity	C 1
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	95%
Water Proofing	100%
Gypsum	40%
Flooring	90%
Window	20%
Door	73%
Wire & Switch work	55%
Internal Paint	0%
External Paint	90%
Snag	5%
Lift	50%



Activity	C2
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	90%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	80%
Window	80%
Door	100%
Wire & Switch work	60%
Internal Paint	0%
External Paint	90%
Snag	5%
Lift	55%



Activity	C 3
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	96%
External Plumbing	0%
Conceal Plumbing	100%
Fabrication	0%
Water Proofing	96%
Gypsum	100%
Flooring	19%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	20%



Expected possession – 20/11/2023

Activity	C 4
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	55%
Conceal Plumbing	100%
Fabrication	67%
Water Proofing	100%
Gypsum	75%
Flooring	40%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	20%
Snag	0%
Lift	60%




Activity	C 5
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	94%
Door	100%
Wire & Switch work	50%
Internal Paint	37%
External Paint	90%
Snag	0%
Lift	90%



Activity	C6
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	90%
Internal Paint	70%
External Paint	90%
Snag	60%
Lift	100%



Activity	C 8
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	65%
Internal Paint	0%
External Paint	90%
Snag	35%
Lift	100%




Activity	C 9
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	98%
Door	100%
Wire & Switch work	90%
Internal Paint	73%
External Paint	95%
Snag	60%
Lift	100%



Activity	D1
RCC	100%
Blockwork	95%
External Plaster	60%
Wall Conduit	50%
External Plumbing	30%
Conceal Plumbing	80%
Fabrication	100%
Water Proofing	0%
Gypsum	40%
Flooring	0%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	0%



Activity	D2
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	90%
Internal Paint	55%
External Paint	90%
Snag	55%
Lift	100%



Activity	D3
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	90%
Window	60%
Door	89%
Wire & Switch work	65%
Internal Paint	30%
External Paint	90%
Snag	0%
Lift	90%



Activity	D4
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	70%
Conceal Plumbing	100%
Fabrication	0%
Water Proofing	100%
Gypsum	100%
Flooring	20%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	15%



Activity	D5
RCC	100%
Blockwork	100%
External Plaster	70%
Wall Conduit	100%
External Plumbing	50%
Conceal Plumbing	100%
Fabrication	0%
Water Proofing	94%
Gypsum	100%
Flooring	40%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	10%




Activity	D6
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%



Activity	D8
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%

Building E1



Activity	E1
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	70%
Conceal Plumbing	93%
Fabrication	20%
Water Proofing	100%
Gypsum	98%
Flooring	30%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	50%
Snag	0%
Lift	10%


Building E2




Expected possession – 31/12/2023

Activity	E2
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	35%
Conceal Plumbing	100%
Fabrication	0%
Water Proofing	100%
Gypsum	100%
Flooring	80%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	50%
Snag	0%
Lift	10%


Building F1



Activity	F1
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	65%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	95%
Door	30%
Wire & Switch work	5%
Internal Paint	40%
External Paint	90%
Snag	5%
Lift	25%



Activity	K1
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	100%
Internal Paint	100%
External Paint	100%
Snag	100%
Lift	100%



Expected possession – 31/12/2023

Activity	K2
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	90%
Internal Paint	35%
External Paint	90%
Snag	50%
Lift	95%



Activity	K3
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	100%
Wire & Switch work	85%
Internal Paint	85%
External Paint	95%
Snag	70%
Lift	100%




Activity	K4
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	100%
Door	84%
Wire & Switch work	65%
Internal Paint	52%
External Paint	80%
Snag	45%
Lift	60%



Activity	K5
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	100%
Window	30%
Door	25%
Wire & Switch work	0%
Internal Paint	0%
External Paint	70%
Snag	0%
Lift	90%




Activity	K6
RCC	100%
Blockwork	100%
External Plaster	100%
Wall Conduit	100%
External Plumbing	100%
Conceal Plumbing	100%
Fabrication	100%
Water Proofing	100%
Gypsum	100%
Flooring	98%
Window	70%
Door	66%
Wire & Switch work	50%
Internal Paint	41%
External Paint	80%
Snag	76%
Lift	30%



Expected possession – 31/12/2023

Activity	K7
RCC	100%
Blockwork	100%
External Plaster	40%
Wall Conduit	71%
External Plumbing	0%
Conceal Plumbing	70%
Fabrication	70%
Water Proofing	20%
Gypsum	63%
Flooring	10%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	0%



Expected possession – 24/12/2024

Activity	K8
RCC	10%
Blockwork	0%
External Plaster	0%
Wall Conduit	0%
External Plumbing	0%
Conceal Plumbing	0%
Fabrication	0%
Water Proofing	0%
Gypsum	0%
Flooring	0%
Window	0%
Door	0%
Wire & Switch work	0%
Internal Paint	0%
External Paint	0%
Snag	0%
Lift	0%





For more updates do visit us at www.xrbia.com